

**EAST Search History****EAST Search History (Prior Art)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	1028	73/800	US_PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/08 16:03
L4	7559	"1" and (tub\$4 conduit pipe) near3 (deform\$4 force stress strain pressure bend\$4 flex\$4 deflect\$4) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 16:04
L5	38	3 and (tub\$4 conduit pipe) near3 (deform\$4 force stress strain pressure bend\$4 flex\$4 deflect\$4) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 16:04
L6	7	5 and temperature near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 16:08

S1	488919	(tube conduit pipe). clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 15:53
S2	641397	(tub\$4 conduit pipe). clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 15:54
S3	46602	(tub\$4 conduit pipe) near3 (deform\$4 bend \$4 flex\$4 deflect\$4). clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 15:55
S4	817	S3 and temperature near3 (fluid liquid water flow).clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 15:55
S5	5	S4 and optic\$4 near3 cable.clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 15:56
S6	1225	(tub\$4 conduit pipe) near3 (deform\$4 bend \$4 flex\$4 deflect\$4) near3 (measur\$5 indicat\$4 meter\$4 test \$4 detect\$4 determin \$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/07 16:14
S7	101	S6 and temperature near3 (measur\$5 indicat\$4 meter\$4 test \$4 detect\$4 determin \$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/07 16:18
S8	1	S7 and optic\$4 near3 cable.clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 16:18

S9	24	S7 and optic\$4 .clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 16:19
S10	6	S7 and optic\$4 near3 cable	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 16:20
S11	12	(("5,218,197") or ("5,726,744") or ("6,450,037") or ("6,536,291") or ("6,586,722") or ("6,644,848")).PN.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/08/07 16:58
S12	7559	(tub\$4 conduit pipe) near3 (deform\$4 force stress strain pressure bend\$4 flex \$4 deflect\$4) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect \$4 determin\$4 sens \$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/07 17:00
S13	35	S12 and optic\$4 near3 cable.clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 17:07
S14	10	S13 and (bragg grating)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 17:07
S15	7	S13 and temperature near3 (measur\$5 indicat\$4 meter\$4 test \$4 detect\$4 determin \$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/07 17:10

S16	7	73/760-860	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 17:40
S17	12076	((73/760-860) or (73/862,454- 862,471)).OCLS.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/08/07 17:42
S18	181	S17 and (bragg grating)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/07 17:42
S19	12076	((73/760-860) or (73/862,454- 862,471)).OCLS.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/08/08 08:28
S20	181	S19 and (bragg grating)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/08 08:28
S21	26	S20 and temperature near3 (measur\$5 indicat\$4 meter\$4 test \$4 detect\$4 determin \$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 08:28
S22	7559	(tub\$4 conduit pipe) near3 (deform\$4 force stress strain pressure bend\$4 flex \$4 deflect\$4) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect \$4 determin\$4 sens \$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 08:31

S23	196	S22 and (bragg grating)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/08 08:53
S24	43	S22 and (bragg near2 grating).clm.	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/08/08 08:53
S25	16	S24 and temperature near3 (measur\$5 indicat\$4 meter\$4 test \$4 detect\$4 determin \$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US_PGPUB; USPAT; EPO; JPO	OR	ON	2009/08/08 09:19

8/8/09 4:11:42 PM

C:\Documents and Settings\MNoori\My Documents\EAST\Workspaces\max.wsp